

How’s My Waterway?

Informing the conversation about your waters.

Waterbody Report

North Oconee River

Assessment Unit ID: GAR030701010507

Waterbody Condition:

Good

Existing Plans for Restoration:

Yes

303(d) Listed:

No

Year Reported:

2022

Organization Name (ID):


Georgia Environmental Protection Division (21GAEPD)

What type of water is this?

Stream/creek/river (5 Miles)

Where is this water located?

Jackson County to Sandy Creek



Fishing

Good ▼

Identified Issues for Use

No impairments evaluated for this use.

Other Water Quality Parameters Evaluated

Assessed Good

- Copper
- Fecal Coliform

Probable sources contributing to impairment from 2022:

No probable sources of impairment identified for this waterbody.

Assessment Documents

No documents are available

Plans to Restore Water Quality

What plans are in place to protect or restore water quality?

Links below open in a new browser tab.

Plan	Impairments	Type	Date
<a href="#">North Oconee River (Copper).</a>	Copper	TMDL	2002-02-28
<a href="#">Oconee River Watershed</a>	Fecal Coliform	TMDL	2002-02-28
<a href="#">Tmdl Evaluation for Seventy-Two Stream Segments in the Oconee River Basin for Fecal Coliform</a>	Fecal Coliform, Pathogens	TMDL	2007-04-25